



DETAIL FOR THERMALLY BROKEN FRAME SPECIFICATION

FRAME SPECIFICATION
GALVANNEAL STEEL
CONSTRUCTED WITH INTEGRAL POLYVINYLCHLORIDE(PVC) THERMAL BREAK
FOR USE WITH 1 3/4 DOORS

THERMALLY BROKEN HEAD, JAMB DETAIL



THERMALLY BROKEN MULLION DETAIL



DRAWING:	VHM-00045	DRAWN BY:	MR
HANDS:	N/A	DATE:	May 25, 2012
MATERIAL:	N/A	SCALE:	NOT TO SCALE
ISSUE:		REVISION:	